



ARMY PUBLIC SCHOOL
ASC CENTRE & COLLEGE, BANGALORE – 7
(Affiliated to CBSE Delhi)

BUILDING STRUCTURE SAFETY CERTIFICATE

It is certified that visual inspection of building of Army Public School ASC C&C located in ASC Centre (South) has been carried out and Building No CW-05, CW-58, Vet 3, 7 to 12, 16, 22, 32, 33 and 52 are found visible structurally safe as on date.

Station: Bangalore

Date: Aug 2025.



Singh
AGE B/R
AE (Civ)
AGE B/R-II (C) Bangalor

*blds appears to be safe on prima facie visual inspection.
However fr detailed inspection Structural Audit is
required.*

G E (Central)

ASJP
(Ambareesh Singh, IDSE)
LE
Garrison Engineer (C) BLR

Don't know
Chairman
Army Public School ASC C & C
Bangalore - 07

Sumitha